Installation Instructions – Carbon Heating Foil for Wall and Ceiling Installation

Please follow all installation and safety instructions carefully to ensure safe operation and uniform heat distribution.



Technical diagram: Wiring and length limitations for 48 V carbon heating foil

1. Surface Preparation

The surface must be dry, stable, and load-bearing. For ceiling installations, ensure that the ceiling structure is sufficiently stable. Remove dust, dirt, and oil before installation. Use primer if necessary.

2. Marking the Heating Areas

Mark the installation positions of the heating foils on the wall or ceiling. Maximum total heating circuit length with 2.5 mm² cable: 5.5 m.

3. Planning Cable Routes

Plan cable routes from the control box to the heating foil carefully to avoid damage to the foil.

4. Preparing Cable Channels
Create suitable cable channels in the wall or ceiling for the power supply cables.

5. Electrical Wiring
Install 2.5 mm² supply cables from the control box to the heating foils.

6. Making Connections
Connect the crimp connectors securely to the cables.

7. Installing the Heating Foil
Bond the heating foil evenly without air pockets. Secure all crimp connections properly.

8. Connecting Heating Strips
The heating strips are connected in series. Maximum single strip length: 3.5 m. Maximum total circuit length: 5.5 m.

9. Resistance Measurement
Measure the electrical resistance of each heating surface before covering.

10. Covering the Heating Foil
After testing, the heating foil may be covered with gypsum plaster or filler compound.

11. Electrical Safety
Ensure all electrical connections are professionally insulated and protected.

12. Thermostat Installation
Install a thermostat to regulate room temperature efficiently and safely.

13. Thermal Insulation
Install the heating foil on thermally insulating material to minimize heat loss.

14. Bonding and Fixing
Avoid air pockets beneath the foil to ensure proper heat transfer.

15. Installation in Wet Areas
In wet rooms, ensure compliance with the required IP protection class.

16. Heating Output Check
Verify that the installed heating surface provides sufficient heating capacity.

17. Drying Time
Allow sufficient drying time before skim coating, painting, wallpapering, or cladding.

Following these instructions will ensure safe and efficient installation of the carbon heating foil system.

Rebotherm Energy UG
Ballindamm 3
20095 Hamburg – Germany